

	•			47	49	51
:	Clamp Case	Op1 >=	Op2 >=	Op l leading zeros	Op2 leading zeros	Total leading zeros
45ar	1.	0.100000.0000	0.000010.0000	0	4	4
456	2.	0.010000.0000	0.000100.0000	1	3	4
450	3.	0.001000.0000	0.001000.0000	2	2	4
452	4.	0.000100.0000	0.010000.0000	3	1	4
450	5.	0.000010.0000	0.100000.0000	4	0	4

F16.3






FIG. 4




FIG. 5